

Photograph Schedule



Figure: 1
General view of site boundary



Figure: 2
Large hole in site boundary – H&S risk



Figure: 3
Previous patch repair to site boundary



Figure: 4
Further evidence of large holes in site boundary – H&S risk



Figure: 5
Low level chain link fencing providing no security – H&S risk



Figure: 6
Sharp barbed wire used as a temporary patch repair by site neighbours – H&S risk



Figure: 7
Low level fencing providing limited security from intruders – H&S risk



Figure: 8
Gated access from neighbouring residential property directly into school ground – major H&S risk



Figure: 9
Evidence of insecure site boundary line – H&S risk



Figure: 10
Further evidence of insecure site boundary line– H&S risk



Figure: 11
General view of unsecured east boundary – H&S risk



Figure: 12
General view of unsecured east boundary – H&S risk



Figure: 13
Unsecure and unstable concrete panel fencing – H&S risk



Figure: 14
Insufficient security fencing to main entrance leaves school at risk of intruders entering the site unknowingly – H&S risk



Figure: 15
Entrance gate provides inadequate security to school – H&S risk



Figure: 16
Entrance gate and boundary wall/fence provides inadequate security to school - H&S risk



Figure: 17
Inadequate security fencing to site boundary leaves school at risk of intruders entering the site unknowingly – H&S risk



Figure: 18
Reception airlock with no segregation between reception / office staff and members of the public / intruders – H&S risk