



Arboricultural Report

17 Maltby road
Scunthorpe
DN17 2JE
WIP: 173769/INST434
T.P.O YES

TREES: Crataegus monogyna

DEVELOPMENT CONTROL SECTION	
06 JUN 2016	
DATE RECEIVED	
Referred To	



ON INSPECTION:

A visual inspection was carried out from ground level. The *Crataegus monogyna* was found to be planted in a raised garden to the front of the property with a retaining wall holding back said garden from public footpath. The tree has been reduced in the past which seems to suggest that the issue now is a historic one. The main stem (which has a cavity present) and root system are causing the retaining wall to fail. The retaining wall has had some remedial work carried out to it to try and rectify the stability of the wall which is failing.

N.B if the retaining wall was to fail it could cause serious injury to the public.

RECOMEND:

Section fell as low as possible to ground level and treat remaining stump with a suitable stump killer.

Report compiled by

Colin Moore

Contracts Manager

07765883720