



Survey Legend:

—	Bank Top / Bottom	▬	Building	▬	Building Canopy
▬	Boundary	▬	Surface Changes :		
▬	Canopy/ Shrub Line	▬	Well Defined / Poorly Defined / Undefined		
▬	Trunk Line	▬	eg Conc Edge / Tarmac Edge / Track Edge		
▬	Hedge	—E—	T—		
▬	Wall	—	Overhead Electric / Telephone Cable		
—x—	Fence	—	Drop Kerb / Kerb		
—>—	Foul Water Sewer				
—>—	Surface Water Sewer				

⊕	Borehole	⊠	Trial Pit	⊕	Survey Station
BO	Bollard	GP	Gate Post	SPL	Sign Post Lit
CT	Cable TV	IL	Invert Level	SV	Stop Valve
CL	Cover Level	KO	Kerb Offset	SVP	Soil Vent Pipe
EL	Electric Cover	LP	Lamp Post	TC	Telecom Cover
EP	Electric Post	MH	Man Hole	TL	Traffic Light
ER	Earth Point	MP	Marker Post	TP	Telegraph Pole
FFL	Floor Level	PO	Post	UTL	Unable to Lift
FH	Fire Hydrant	RE	Rodding Eye	VP	Vent Pipe
FP	Flag Pole	RS	Road Sign	WM	Water Meter
G	Gully	RWP	Rain Water Pipe	WO	Wash Out
GA	Gas Cover	SP	Sign Post		

Notes:

1. Survey undertaken May 2020.
2. Physical boundary features shown on this survey do not necessarily represent the legal boundaries.
3. Survey Plotted to assumed local metric grid and datum.

Rev.	Description	Date

Title:

TOPOGRAPHICAL SURVEY

LAND OFF LOW GARTH
BOTTESFORD
SCUNTHORPE

G Carnaby			
Approved :		Drawn :	S.Garton
Date :	04.05.20	Scale :	1:200
Digital file:	1954 Survey.dwg	Original Size:	A2
Drawing No.:	1954/001	Rev:	

shire surveys

Westfield Cottage, 7 Crowle Bank Road
Althorpe, North Lincolnshire, DN17 3HZ
Tel : 01724 783078
Email : office@shiresurveys.com