


CAUTION ASBESTOS HAZARD
 Up until the year 2000, asbestos was used extensively in the construction industry as a means of fireproofing and insulation for buildings. While its use has been completely banned since 1999, it is still commonly found in older buildings, and it can be exposed during repair, maintenance, or demolition work. Asbestos or asbestos based materials can be found in asbestos cement coatings, insulated coatings, insulation boards, lagging pipes, loft insulation, floor cavities, suspended ceiling tiles, floor tiles, down pipes, gutters and roofs etc...
PLEASE REFER TO THE EMPLOYERS ASBESTOS REGISTER



Ref.	By	Revisions	Date
-	-	-	-/-



Employer:
**Humberstone Police
 Joint Estates Services**

Location & Project
**Internal Alterations & Extension
 Winterton Fire Station, Earlsgate Rd,
 Winterton.**

Drawing Title
Existing Roof Plan

Drawn: C.A. Barr
 Date: 10.10.21
 Scale: 1:50 at A1

Drawing No:
A1-21023-07

Revised:
 -

C. A. Barr Architects

RIBA Chartered Practice
 SURVEYING, PLANNING, SUPERVISION & PROJECT PROCUREMENT
 14 THE LINC, 4th FLOOR, KINGSTON UPON HULL, EAST YORKSHIRE, HU1 4JX
 Tel: 01482 355000 Fax: 01482 355009 Mobile: 07741 557573
 Registered Office: 1 Parliament Street, Kingston upon Hull, HU1 2AS
 Registered in England/Company No: 0252321 Registered Company Name: C.A. Barr Limited

DO NOT SCALE FROM THIS DRAWING. IF IN DOUBT ASK.
 All dimensions are to be checked on site prior to the commencement of any work, and any error or omission immediately reported to C.A. Barr Ltd. All revisions shown are approximate only and their contents are to establish their true position prior to the commencement of any work.